

20536

CALL TO		PHONE	
VENTINGTON LAKES SECTION 7		MECHANIC	
ADDRESS ASSOCIATION		HELPER	
CITY			
JOB NAME AND LOCATION		☐ DAY WORK ☐ CONTRACT ☐ EXTRA	
DESCRIPTION OF WORK			
Old exp. 29-36 plus pool Test all backflow prevention devices			
SERIAL NUMBER		PRICE	AMOUNT

[illegible]

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7280 AMBERLY LN
DELRAY BEACH, FL 33446-2960
Account #: 1000053902
Meter Serial #: 0099956959
MXU #: 90249248

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Model: 975XL
Serial#: 3242584
Manufacturer: WILKINS
Location: BLDG 29 IN FRONT OF UNIT 108 BEHIND FENCE

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 8.00	2nd Check Valve Pressure 2.20	Relief Valve 2.40
---	---	-----------------------------

Backflow Inspection Comments

No Comments Selected.	No Comments Selected.	No Comments Selected.
-----------------------	-----------------------	-----------------------

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7300 AMBERLY LN
DELRAY BEACH, FL 33446-2963
Account #: 1000053901
Meter Serial #: 0086486271

MXU #: 92778036

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Model: 975XL
Serial#: 33412269
Manufacturer: WILKINS
Location: BLDG 30 FRONT OF BLDG BY UNIT 103 BEHIND FENCE

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 7.40

2nd Check Valve Pressure 2.00

Relief Valve 2.00

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7320 AMBERLY LN
DELRAY BEACH, FL 33446-2941
Account #: 1000053903
Meter Serial #: 0088866289

MXU #: 92775698

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Model: 975XL
Serial#: 2960443
Manufacturer: WILKINS
Location: BLDG 31 FRONT OF BLDG BY FENCE

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 7.00	2nd Check Valve Pressure 2.00	Relief Valve 3.00
---	---	-----------------------------

Backflow Inspection Comments

No Comments Selected.	No Comments Selected.	No Comments Selected.
-----------------------	-----------------------	-----------------------

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7340 AMBERLY LN
DELRAY BEACH, FL 33446-2944
Account #: 1000053905
Meter Serial #: 0088892210

MXU #: 92778500

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 32 FRONT OF 107

Model: 975XL
Serial#: 3242576

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 7.40

2nd Check Valve Pressure 2.40

Relief Valve 2.00

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7341 AMBERLY LN
DELRAY BEACH, FL 33446-2992
Account #: 1000053907
Meter Serial #: 0088781240

MXU #: 92778512

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 33 FRONT OF 103

Model: 975XL
Serial#: 3135274

Reason for test: ☐ new ☒ existing

FAILED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 0.00

2nd Check Valve Pressure 0.00

Relief Valve 0.00

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **FAILED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.

The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7321 AMBERLY LN
DELRAY BEACH, FL 33446-2991
Account #: 1000053910
Meter Serial #: 0088866326

MXU #: 92778688

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 34 FRONT OF BLDG BY FENCE
Model: 975XL
Serial#: 3407240

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 6.80

2nd Check Valve Pressure 2.60

Relief Valve 2.40

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNT LKS SECT 4 ASSOC
Property Address: 7301 AMBERLY LN
DELRAY BEACH, FL 33446-2906
Account #: 1000053906
Meter Serial #: 0088781257

MXU #: 92777334

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 35 FRONT OF BLDG BY FENCE UNIT 103
Model: 975XL
Serial#: 3130730

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure 7.00

2nd Check Valve Pressure 3.00

Relief Valve 2.40

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7281 AMBERLY LN
DELRAY BEACH, FL 33446-2903
Account #: 1000053904
Meter Serial #: 0100886061

MXU #: 89699336

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 36 FRONT R OF BLDG BY FENCE
Model: 975 XL
Serial#: 2798422

Reason for test: ☐ new ☒ existing

FAILED

Assembly Test Information

Test Date: 11/04/2025

1st Check Valve Pressure
0.00

2nd Check Valve Pressure
0.00

Relief Valve
0.00

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **FAILED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7351 AMBERLY LN
DELRAY BEACH, FL 33446-2950
Account #: 1000054022
Meter Serial #: 0086284935

MXU #: 92883418

Assembly Information

Type: REDUCED PRESSURE
Size:
Manufacturer: WATTS
Location: BY WALK AT AMBERLY POOL

Model: 009
Serial#: 26189

PASSED

Test Date: 11/04/2025

Assembly Test Information

1st Check Valve Pressure 9.00

2nd Check Valve Pressure 2.00

Relief Valve 2.20

Backflow Inspection Comments

No Comments Selected.

No Comments Selected.

No Comments Selected.

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467

Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.