

ACCURATE PLUMBING SERVICES, INC.

8525 El Paso Drive
LAKE WORTH, FLORIDA 33467
(561) 968-0336

JOB INVOICE

20586

BILL TO <i>Huntington Lakes Section 4 Association</i>		CUSTOMERS ORDER NO.	DATE ORDERED
ADDRESS		ORDER TAKEN BY	DATE PROMISED ☐ A.M. ☐ P.M.
CITY		PHONE	
JOB NAME AND LOCATION <i>Buildings 33 & 36</i>		MECHANIC	
DESCRIPTION OF WORK <i>on 11/4/25 these 2 buildings failed the backflow certification tests. We had to open the devices</i>		HELPER	
		☐ DAY WORK	
		☐ CONTRACT	
		☐ EXTRA	

QUANT.	DESCRIPTION OF MATERIAL USED	PRICE	AMOUNT
	<i>up - clean them & Reassemble them. NO parts were needed. We tested them & they passed so we certified them & filed the paper work with PBC Water Utilities.</i>		

Bldg. 33

labor 32500

Bldg. 36

labor 32500

2 2" tests + certifications

\$158.00

HOURS	LABOR	AMOUNT	TOTAL MATERIALS
	MECHANICS @		
	HELPERS @		
			TOTAL LABOR 650.00
			tests 158.00
I hereby acknowledge the satisfactory completion of the above described work.		TOTAL LABOR	TAX
SIGNATURE		DATE COMPLETED <i>12/23/25</i>	TOTAL 808.00

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7341 AMBERLY LN
DELRAY BEACH, FL 33446-2992
Account #: 1000053907
Meter Serial #: 0088781240

MXU #: 92778512

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 33 FRONT OF 103
Model: 975XL
Serial#: 3135274

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 12/23/2025

1st Check Valve Pressure	2nd Check Valve Pressure	Relief Valve
7.60	2.40	3.00

Backflow Inspection Comments

1st Check Valve Pressure	2nd Check Valve Pressure	Relief Valve
☒ Cleaned	☒ Cleaned	☒ Cleaned

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.

The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.

Palm Beach County - Water Utilities Department

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer Name: HUNTINGTON LKS ASSOC #4
Property Address: 7281 AMBERLY LN
DELRAY BEACH, FL 33446-2903
Account #: 1000053904
Meter Serial #: 0100886061

MXU #: 89699336

Assembly Information

Type: REDUCED PRESSURE
Size: 2.00
Manufacturer: WILKINS
Location: BLDG 36 FRONT R OF BLDG BY FENCE
Model: 975 XL
Serial#: 2798422

Reason for test: ☐ new ☒ existing

PASSED

Assembly Test Information

Test Date: 12/23/2025

1st Check Valve Pressure 7.00	2nd Check Valve Pressure 2.20	Relief Valve 3.00
---	---	-----------------------------

Backflow Inspection Comments

1st Check Valve Pressure ☒ Cleaned	2nd Check Valve Pressure ☒ Cleaned	Relief Valve ☒ Cleaned
--	--	--

As the tester of record, I affirm this test as **PASSED**

Additional comments or repairs made / materials (parts) used:

Tester Information

Tester Name: FLEMING, ROGER
Tester License Expiration: 11/30/2026
Tester Certification#: PR_9020
Test Kit Serial #: 08020311
Test Kit Date Tested for Accuracy: 01/28/2026
Test Kit Manufacturer: MIDWEST
Testing Company Name: ACCURATE PLUMBING
Testing Company Phone: (561) 968-0336
Testing Company Address: 8525 EL PASO DR, LAKE WORTH, FL 33467
Test Kit Model: 830

The above tester certifies that all information submitted for this report is true and accurate.
The backflow prevention assembly detailed above has been tested and maintained as required and is certified to be operating within acceptable parameters.